

# **Appendix B**

## **Diving Inspection Report**

February 5, 2007

Bergmann Associates  
1 Computer Drive South  
Albany, New York 12205

Attn: Mr. Peter Melewski

Re: Underwater Investigation of the Poughkeepsie Railroad Bridge  
McLaren File No. 106158

Dear Mr. Melewski:

### **Introduction**

McLaren Engineering Group was retained by Bergmann Associates to perform an underwater investigation of the submerged portions of the substructures for Pier 2 through Pier 5 for the Poughkeepsie Railroad Bridge. The investigation was performed from November 2 to November 7, 2006. Also please find attached Appendix – A, Photographs, and Appendix – B, Figures referenced during this report.

### **Scope of Work**

All in-water pier substructures received a visual inspection from Mean High Water line (MHW) to the mudline. Water depth were measured and recorded at eight points around the perimeter of the piers along the mudline. Probes were taken into the timber cribbing and grillage. Mudline elevation and composition were recorded. Additional investigation was performed using a “DIDSON” Sonar Camera on November 21, 2006 at Pier 2 to determine the extent of the void area observed during the initial investigation.

### **Methodology**

The dive team conducting the investigation was composed of a Professional engineer diver, a diver and a diver tender. Dive operations were conducted from either a thirty-foot aluminum boat or a twenty-two foot fiberglass dive boat. Diving was performed using surface supplied equipment with constant two-way radio communication and real-time video recording. Divers visibility during the investigation was limited to three inches or less, making visual observation very limited. Most of the inspection was performed using tactile investigation skills. Due to high current velocity, inspections time was limited to hours of slack current.

Offices: New York, Maryland, Florida, Connecticut, California, Virginia

Licensed in:

Arizona • Arkansas • California • Colorado • Connecticut • Delaware • District of Columbia • Florida • Georgia • Illinois  
Indiana • Kentucky • Louisiana • Maryland • Massachusetts • Michigan • Minnesota • Mississippi • Missouri • Nebraska  
Nevada • New Hampshire • New Jersey • New York • North Carolina • Ohio • Oklahoma • Oregon • Pennsylvania  
South Carolina • Tennessee • Texas • Utah • Vermont • Virginia • Washington • West Virginia • Wisconsin

**M. G. McLAREN, P.C.**

100 Snake Hill Road

West Nyack, New York 10994

Phone (845) 353-6400

Fax (845) 353-6509

e-mail: [mgmclaren@mgmclaren.com](mailto:mgmclaren@mgmclaren.com)

On the web: [www.mgmclaren.com](http://www.mgmclaren.com)

## Bridge History

The Pennsylvania Railroad officially started the initial construction of the Poughkeepsie Railroad Bridge in 1873. However, actual bridge construction started in 1876 by the American Bridge Company who built Pier 2, installed the cribbing for Pier 3, and partially completed construction on the timber cribbing for Pier 4. Construction was suspended from 1876 to 1886 when construction was resumed by the Union Bridge Company, who modified the design and reworked Pier 2 and completed the remainder of the bridge with the first traffic across the bridge on January 1, 1889.

The overall length of the bridge is approximately 6,767 feet (see Figure 1). The main bridge (Pier 0 to Pier 7) consists of seven deck truss spans (Photo 1), three cantilever spans of 548 ft each, two connecting spans of 525 ft each and two shore spans of 201 ft each for a total river span of 3,094 ft (see Figure 2). The east and west bridge approaches are comprised of a combination of deck truss and girder spans that are supported by steel bents.

Additional work to strengthen the bridge to accommodate heavier rail loading was completed in 1907. General maintenance and several track changes were performed in subsequent years until a fire occurred on the east approach span of the bridge in 1974 causing damage that ended all rail services over the bridge.

## Typical Substructure Construction

Typical substructure components of the piers consist of a heavy timber crib structure that was used as a deep dredging system. The cribbing is essentially a bottomless box and was constructed of several layers of 12 in. by 12 in. timbers positioned horizontally and fastened with steel pins, typically the exterior was then sheathed with vertical timber planking to complete the structure. The cribbing structures measures approximately 60 ft wide by 100 ft long at the bottom (see Figure 3), and tapers along the east and west faces to 50 ft wide by 100 ft long at the top. The timber cribbing was partially built on land then floated out in the river where it was positioned, sunk by filling the weighting pocket with stone and built up to the required elevation as dredges worked to remove material from the interior dredging wells until the bottom of the crib structure was founded on firm soil at approximately 130 ft below the surface of the river. The dredging wells were then filled and leveled with concrete to provide a stable foundation for the timber grillage layer.

When the concrete filled timber cribbing installation was complete the next step was constructing and placing a floating caisson over the cribbing. The caisson was designed with the bottom serving as a mat of timber grillage and was constructed of six layers of 12 in. by 12 in. timbers (see Figure 4). Once the caisson was floated into position over the previously placed cribbing, construction of the masonry faced concrete pier began within the floating caisson. As the pier construction progressed the weight of the pier gradually sunk the caisson until it rested on the cribbing. Once the masonry and concrete pier was completed the caisson was flooded and the sides were removed leaving the completed masonry and concrete portion of the pier resting on the timber grillage. The finished overall dimensions of the concrete filled masonry piers are approximately 25 ft wide by 90 ft long.

## Observations

### Pier 2

Pier 2 is located nearest to the western shoreline of the river (Photo 2 and Photo 3). Construction of Pier 2 varies slightly from the other piers (see Figure 5). Construction of the substructure was partially completed when the project was postponed, redesigned and work eventually started again by a different Contractor. A bottomless timber caisson was constructed around the existing pier and pumped dry, then partial demolition of the existing pier was performed, the new masonry and concrete pier constructed over the remains of the previously pier foundation and then the interior of the caisson was filled with concrete (see Figure 6).

The stone masonry portion of the pier is generally in fair condition. Typical deficiencies include intermittent areas of missing mortar from between the joints, with penetration from 4 in. to 12 in. deep, and moderately spalled and loose coping stones on the south face of the pier. Moderate efflorescence and rust staining were also evident on the face of the masonry.

The timber cribbing and grillage typically exhibit moderate rot and loss of cross sectional area with gaps between the timbers averaging 1 in. to 2 in. wide. Intermittent penetrations into the gaps of the cribbing were taken and typically varied from 12 in. to over 3 ft deep. The outer layer of vertical timber sheeting is missing from around the entire pier. Intermittent missing pieces of 12 in by 12 in. timber cribbing were also observed. A significant horizontal void area was observed behind the outermost layer of the timber crib wall, extending along the east, south and west faces of the pier. The voids are located approximately 29 ft below the water surface and extend approximately 16 ft along the south face and 56 ft along the west face. The void in the timber cribbing is 2 ft high at the south west corner and tapers down to 2 in. as it progresses along the south and west elevations. Penetrations in the void varied from 3 ft to more than 6 ft deep. The maximum height of the void on the inside of the timber cribbing at the southwest corner is unknown.

Additional investigation was performed to determine the depth of the void. A dive crew equipped with a "DIDSON" Sonar Camera performed a real time sonar survey of the void area. Interpretation of the sonar images revealed that only the outer layer of weighting pockets has been compromised revealing the stone fill (Photo 4). The inner timber wall and transverse ties appeared to be in place (Photo 5, and Photo 6). It was not possible to visually inspect or probe the timber on the interior pockets to determine their condition.

The mudline generally consists of silt and sand over scattered rip rap stone with concrete and steel debris. No signs of scour were observed in the vicinity of the pier. Water depth varied from 39 ft to 66 ft around the pier.

### Pier 3

Pier 3 also has a slightly different construction. The timber grillage mat was built up of 14 layers of 12 in. by 12 in. timbers in order to bring the foundation up to the required elevation (see Figure 7).

The stone masonry portion of the pier is generally in fair condition (Photo 7 and Photo 8). Typical deficiencies include intermittent areas of missing mortar from between the joints, with penetration from 2 in. to 14 in. deep. Moderate efflorescence and rust staining were also evident on the face of the masonry.

The timber cribbing and grillage typically exhibit moderate rot and loss of cross sectional area with gaps between the timbers averaging 1 in. to 2 in. wide. Intermittent penetrations into the gaps of the cribbing were taken and typically varied from 12 in. to over 4 ft deep. The outer layer of vertical timber sheeting is missing from around the entire pier. Minor areas of intermittent missing pieces of 12 in by 12 in. timber cribbing from the outer layer, up to 4 ft long were also observed.

A significant void was discovered along the east elevation at approximately 22 feet below the water surface. The void was located at the interface between the timber grillage and the cribbing structure. The void measured approximately 4 ft high at the southeast corner and tapered down to 2 ft high at the north end of the pier. Penetrations into the void varied and were approximately 2 ft deep at the northwest corner and up to 6 ft deep at the southwest corner.

The mudline generally consists of silt and sand over scattered rip rap stone with concrete and steel debris. No signs of scour were observed in the vicinity of the pier. Water depth varied from 38 ft to 51 ft around the pier.

#### **Pier 4**

Constructions of the pier substructural elements are as described above under "**Typical Substructure Construction**". The stone masonry portion of the pier is generally in fair condition (Photo 9 and Photo 10). Typical deficiencies include intermittent areas of missing mortar from between the joints, with penetration from 4 in. to 16 in. deep.

The timber cribbing and grillage typically exhibit moderate rot and loss of cross sectional area with gaps between the timbers averaging 1 in. to 2 in. wide. Intermittent penetrations into the gaps of the cribbing were taken and typically varied from 12 in. to 2 ft deep. The outer layer of vertical timber sheeting is missing from around the entire pier. Minor areas of intermittent missing pieces of 12 in by 12 in. timber cribbing from the outer layer were also observed.

The mudline generally consists of silt and sand over scattered rip rap stone with concrete and steel debris. No signs of scour were observed in the vicinity of the pier. Water depth varied from 39 ft to 58 ft around the pier.

#### **Pier 5**

Pier 5 is located nearest to the eastern shoreline of the river (Photo 11 and Photo 12). Constructions of the pier substructural elements are as described above under "**Typical Substructure Construction**".

The stone masonry portion of the pier is generally in fair condition. Typical deficiencies include intermittent areas of missing mortar from between the joints, with penetration from 2 in. to 12 in. deep. Moderate efflorescence and rust staining were also evident on the face of the masonry.

The timber cribbing and grillage typically exhibit moderate rot and loss of cross sectional area with gaps between the timbers averaging 1 in. to 2 in. wide. Intermittent penetrations into the gaps of the cribbing were taken and typically varied from 12 in. to over 3 ft deep. The outer layer of vertical timber sheeting is missing from around the entire pier. Minor areas of intermittent missing pieces of 12 in by 12 in. timber cribbing from the outer layer, were also observed.

The mudline generally consists of silt and sand over scattered rip rap stone with concrete and steel debris. No signs of scour were observed in the vicinity of the pier. Water depth varied from 42 ft to 54 ft around the pier.

### **Conclusions & Recommendations**

It is recommended to repair the void areas at Pier 2 and Pier 3 to stop the loss of fill from within the cribbing and restore structural integrity. These deficiencies are not an emergency or a structural stability issue at this time; however, the repairs are needed to provide long-term protection and insure stability. It is recommended that these repairs be completed within the next five years to prevent accelerated deterioration of the substructures. We strongly recommend that the deteriorated portions of Piers 2 and 3 be inspected on an annual basis until repairs are made, to arrest or respond to any sudden change of these conditions. It is our intent to avoid any dramatic increase in rehabilitation costs due to lack of attention. It is also recommended to perform an underwater inspection just prior to repair construction to confirm that the extent of deterioration has not changed.

Typically repairs to the voids involve sealing the outer surface of the void by installing formwork or grout bags. The void area is then pumped full with concrete. Estimated construction cost for these repairs is approximately \$750,000 to \$1,500,000. After repairs have been completed the piers should be regularly inspected at five-year intervals to monitor the deterioration of the substructure elements and recommend any additional repairs.

Permits for the repair construction will be required from various state and federal agencies. Since the permitting process approval may take an unusually long time (over 1 year), it is recommended that work on submitting the permits begin immediately so as to not delay the repairs.

Appendix A

Photographs





Photo 1 – Overall view of the river spans of the bridge, looking north.



Photo 2 – Pier 2 west and north elevation.





Photo 3 – Pier 2, south and east elevation.




Photo 4 – Pier 2, west face, south end, sonar image from interior of the void showing large stone fill.




Photo 5 – Sonar image from interior of void showing inner wall timbers in place.




Photo 6 – Sonar image showing transverse timber tie and inner wall in place.



Photo 7 – Pier 3, north and west elevation of the pier.



Photo 8 – Pier 3, south and east face of the pier.





Photo 9 – Pier 4, north and west elevation of the pier.



Photo 10 – Pier 4, south and east elevation of the pier.





Photo 11 – Pier 5, north and west elevation of the pier.




Photo 12 - Pier 5, south and east elevation of the pier.

# Appendix B


## Figures









WEST

EAST








BENTS OF WEST APPROACH  
SHOWING  
ARRANGEMENT OF REINFORCEMENT



BENTS OF EAST APPROACH  
SHOWING  
ARRANGEMENT OF REINFORCEMENT

FIG.-1

PENN CENTRAL






C. N. E. RAILWAY  
OPERATED BY THE  
N. Y. N. H. & H. R. R.  
GENERAL PLAN  
OF  
POUGHKEEPSIE BRIDGE  
**FIG.-2**

— POUCHKEEPSIE BRIDGE —

— GRID - PIER N° 5 —

— Scale 1/2" = 10' — Dec 20 1911 —

— UNION BRIDGE —





mf 68905

FIG.-3



#134



Fig-4



PIER N° 2  
 SCALE: 1/8" = 1'-0"  
 UNION BRIDGE CO. PHARMACIA N.Y.




MF 68887

FIG-5



Used for estimating quantities  
of masonry for Special Franchise Taxes

Jan 1918

JSM



All pockets were filled  
with concrete  
See O'Rourke's on  
The Construction of the  
Long Point Bridge



This section assumed  
to have been used below Elev. -30

— COFFER-DAM — PIER-N°2 —

— DRAWING NO. 207-01 — Scale 1/2" = 1 foot —








FIG-6

#125

Drawn B.N.





Used for estimating  
for special franchise

All caissons assumed  
to this one.

— FLOATING-CAISSON —

— PIER N'S —

— HIGHWAY BRIDGE C' —



MF 68911

FIG-7

M.P.: 29.08

REGION: 8 COUNTY: 6

FEATURE CARRIED: Poughkeepsie RR Bridge

FEATURE CROSSED: Hudson River

GENERAL RECOMMENDATION: 002 PRR - 3

003 PRR - 3

004 PRR - 4

005 PRR - 4

New York State Department of Transportation

# 2006 DIVING INSPECTION

Begin Abutment  Pier (s) 002-PRR, 003-PRR  End Abutment  
004-PRR, 005-PRR

FLAGS: <input type="checkbox"/> RED <input type="checkbox"/> RED PIA	<input type="checkbox"/> YELLOW	<input type="checkbox"/> SAFETY <input type="checkbox"/> SAFETY PIA	<input checked="" type="checkbox"/> NONE <input type="checkbox"/> REMOVAL <input type="checkbox"/> INACTIVATION
---	---------------------------------	--	---

Prime Consultant:



**McLaren**  
ENGINEERING  
GROUP

Phone (845) 353-6400 Fax (845) 353-6509

REVIEWED BY:

*George F. Assis*  
George F. Assis

TITLE: Quality Control Engineer, PE# 073077

BD-400(9/97)




# NYS DOT REGION 8



- ① COLUMBIA
- ② DUTCHES
- ③ ORANGE
- ④ PUTNAM
- ⑤ ROCKLAND
- ⑥ ULSTER
- ⑦ WESTCHESTER

**BRIDGE # 29.08**

**General Map**



**BRIDGE # 3359690**

**Bridge Location Plan**

# DIVE INSPECTION REPORT



BRIDGE DIVING INSPECTION AND CONDITION REPORT

FEATURE CARRIED Poughkeepsie RR Bridge

FEATURE CROSSED Hudson River

ON-SITE ENGINEER James V. Green

DIVER James V. Green

ON-SITE P.E. James V. Green

P.E. No. 078453 STATE NY


BRIDGE MILE POINT

R	C									
8	6	2	9	.	0	8				
1	2	3	4	5	6	7	8	9		

SIGNATURE 

YEAR				MONTH		DAY	
2	0	0	6	1	1	0	7
10	11	12	13	14	15	16	17


SPAN #	UNIT CODE	GENERAL											CONCRETE					MASONRY				TIMBER				STEEL			UNIT RECOMMENDATION	UNIT WORK URGENCY INDEX	UNIT DIVING INSPECTION FREQUENCY	CONTINUATION
		VOIDS	HOLES	STRUCTURAL DAMAGE	NON-STRUCTURAL DAMAGE	DISPLACEMENT	MISSING ELEMENTS	LOSS OF FILL	EROSION	SCOUR	DEBRIS	STRUCTURAL CRACKS	NON-STRUCTURAL CRACKS	SPALLS	EROSION/SCALING	CONSTRUCTION DEFECTS	GROUT LOSS	MISSING UNITS	BROKEN UNITS	SPLITTING	MARINE BORERS	ROT	FASTENERS	MISSING ELEMENTS	DETERIORATION	CONNECTIONS						
18	19	20	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53
0	0	2																														
P	R	R	3	4	4	4	4	4	3	7	6	5	9	9	9	4	7	4	7	6	4	7	4	4	4	4	8	8	3	5	2	Y
0	0	3																														
P	R	R	3	4	4	4	4	4	3	7	6	5	9	9	9	4	7	4	7	6	4	7	4	4	4	4	8	8	3	5	2	Y
0	0	4																														
P	R	R	4	4	4	4	5	4	5	7	6	5	9	9	9	4	7	4	7	6	4	7	4	4	4	4	8	8	4	8	5	Y
0	0	5																														
P	R	R	4	4	4	4	5	4	5	7	6	5	9	9	9	4	7	4	7	6	4	7	4	4	4	4	8	8	4	8	5	Y

QC ENGINEER   
P.E. # 073077  
DATE 10/22/07

BRIDGE DIVING INSPECTION AND CONDITION REPORT

FEATURE CARRIED Poughkeepsie RR Bridge FEATURE CROSSED Hudson River  
 ON-SITE ENGINEER James V. Green DIVER James V. Green  
 ON-SITE P.E. James V. Green  
 P.E. No. 078453 STATE NY

R		C		BRIDGE MILE POINT									
8	6	2	9	.	0	8							
1	2	3	4	5	6	7	8	9					

SIGNATURE 

YEAR				MONTH		DAY	
2	0	0	6	1	1	0	7
10	11	12	13	14	15	16	17

SPAN #	18	19	20	UNIT CODE	21	22	23
	0	0	2		P	R	R

	54	COMMENTS	
Recommended Further Investigation	Y		
Dive Comments	Y	Swift current, dive during slack.	
Work Recommendation	Y	Repair void areas within the timber cribbing to prevent loss of fill. Repoint stone masonry joints.	
Safety Flag			
Structural Flag			
Structural Flag Condition			
	55	56	57

Structural Flag Date	YEAR	MONTH	DATE	Safety Flag Date	YEAR	MONTH	DATE	
	58	59	60	61	62	63	64	65
					66	67	68	69
					70	71	72	73




BRIDGE DIVING INSPECTION AND CONDITION REPORT

FEATURE CARRIED Poughkeepsie RR Bridge FEATURE CROSSED Hudson River  
 ON-SITE ENGINEER James V. Green DIVER James V. Green  
 ON-SITE P.E. James V. Green  
 P.E. No. 078453 STATE NY

R		C	
8	6		
1	2		

BRIDGE MILE POINT								
2	9	.	0	8				
3	4	5	6	7	8	9		

SIGNATURE 

YEAR				MONTH		DAY	
2	0	0	6	1	1	0	7
10	11	12	13	14	15	16	17

SPAN #

18	19	20
0	0	3

UNIT CODE

21	22	23
P	R	R

54	COMMENTS
Y	Recommended Further Investigation
Y	Dive Comments
Y	Work Recommendation
	Safety Flag
	Structural Flag
	Structural Flag Condition

Swift current, dive during slack.

Repair voids within the timber grillage to prevent loss of fill.  
Repoint stone masonry joints.

Structural Flag Date

YEAR				MONTH		DATE	
58	59	60	61	62	63	64	65

Safety Flag Date


YEAR				MONTH		DATE	
66	67	68	69	70	71	72	73

BRIDGE DIVING INSPECTION AND CONDITION REPORT

FEATURE CARRIED Poughkeepsie RR Bridge  
 ON-SITE ENGINEER James V. Green  
 ON-SITE P.E. James V. Green  
 P.E. No. 078453 STATE NY

FEATURE CROSSED Hudson River  
 DIVER James V. Green

R		C		BRIDGE MILE POINT								
8	6	2	9	.	0	8						
1	2	3	4	5	6	7	8	9				

SIGNATURE 

YEAR				MONTH		DAY	
2	0	0	6	1	1	0	7
10	11	12	13	14	15	16	17

SPAN #	18	19	20	UNIT CODE	21	22	23
	0	0	4		P	R	R

	54	COMMENTS	
Recommended Further Investigation	N		
Dive Comments	Y	Swift current, dive during slack.	
Work Recommendation	Y	Repoint stone masonry joints.	
Safety Flag			
Structural Flag			
Structural Flag Condition			
	55	56	57

Structural Flag Date	YEAR				MONTH		DATE	
	58	59	60	61	62	63	64	65

Safety Flag Date	YEAR				MONTH		DATE	
	66	67	68	69	70	71	72	73

BRIDGE DIVING INSPECTION AND CONDITION REPORT

FEATURE CARRIED Poughkeepsie RR Bridge FEATURE CROSSED Hudson River  
 ON-SITE ENGINEER James V. Green DIVER James V. Green  
 ON-SITE P.E. James V. Green  
 P.E. No. 078453 STATE NY

R		C		BRIDGE MILE POINT										
8	6	2	9	.	0	8								
1	2	3	4	5	6	7	8	9						

SIGNATURE 

YEAR				MONTH		DAY	
2	0	0	6	1	1	0	7
10	11	12	13	14	15	16	17

SPAN #	18	19	20	UNIT CODE	21	22	23
	0	0	5		P	R	R

	54	COMMENTS	
Recommended Further Investigation	N		
Dive Comments	Y	Swift current, dive during slack.	
Work Recommendation	Y	Repoint stone masonry joints.	
Safety Flag			
Structural Flag			
Structural Flag Condition			
	55	56	57

Structural Flag Date	YEAR	MONTH	DATE	Safety Flag Date	YEAR	MONTH	DATE	
	58	59	60	61	62	63	64	65
					66	67	68	69
					70	71	72	73



NYS DOT BRIDGE DIVING  
INSPECTION & CONDITION REPORT

R C MP  
8 6 2 9 . 0 8

SHEET 6 OF 35  
DATE 11/07/06

**GENERAL BIN SUMMARY**

SUPERSTRUCTURE DESCRIPTION	Total No. of Spans: <u>74</u>	Load Path: <input type="checkbox"/> Redundant <input checked="" type="checkbox"/> Non-Redundant	Dir/Orient: <u>E/W</u>
Primary Member Material:	<input checked="" type="checkbox"/> Steel	<input type="checkbox"/> Iron	<input type="checkbox"/> Concrete <input type="checkbox"/> Timber <input type="checkbox"/> Other:
Primary Member Type:	<input type="checkbox"/> Rolled Girder	<input type="checkbox"/> PL Girder	<input type="checkbox"/> Box Girder <input checked="" type="checkbox"/> Truss <input type="checkbox"/> Frame <input type="checkbox"/> Arch <input type="checkbox"/> Pipe <input type="checkbox"/> Slab
	<input checked="" type="checkbox"/> Other: Built-up riveted steel girders.		
Plan Review: Plans agree with field conditions?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No: Explain:		

**SITE CONDITIONS**

Evidence of High Water?	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes: Approx. height above present water level? <u>1.5 ft</u>
Underwater Visibility:	<input type="checkbox"/> Good	<input type="checkbox"/> Fair <input checked="" type="checkbox"/> Poor
Tidal Waters?	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes
Low Freeboard?	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes
Protective Devices?	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes: Quantity _____ Type: _____ SSU#:
Current:	<input type="checkbox"/> Negligible	<input type="checkbox"/> Up to 1.0 fps <input checked="" type="checkbox"/> Up to 2.0 fps <input type="checkbox"/> 2.0 to 4.0 fps <input type="checkbox"/> Over 4.0 fps: Estimated Current= _____
Marine Growth:	<input checked="" type="checkbox"/> Negligible	<input type="checkbox"/> Moderate <input type="checkbox"/> Heavy <input type="checkbox"/> Blast Cleaning Required: Total area cleaned= _____
Type:	<input checked="" type="checkbox"/> Algae	<input type="checkbox"/> Aquatic Plants/Grasses <input type="checkbox"/> Zebra Mussel <input type="checkbox"/> Barnacles <input type="checkbox"/> Other:
Polluted Water?	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes: Explain:

**ACTIVITY LOG**

Inspection Access:	<input checked="" type="checkbox"/> Boat	<input type="checkbox"/> Shore	<input type="checkbox"/> Bridge Deck	<input type="checkbox"/> Other:
Boat Launch Location	( <u>N/A</u> )	Whites Marine, Hudson, NY		
Unusual Conditions:	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes: Explain:		
Special Contact(s) for Access or Coordination:	<input checked="" type="checkbox"/> No	<input type="checkbox"/> Yes; Name(s), Organization, Address and Phone Number(s):		

Insp. Consultant:  M.G. McLaren, P.C.      Diving Subcontractor:  None

Date	Arrival Time	Depart. Time	Dive Hours	Temp. Range	Weather	Remarks
11/02/06	7:30 AM	3:30 PM	5	42 -55 F	Clear	U/W Inspection
11/03/06	7:30 AM	3:30 PM	5	42 -55 F	Clear	U/W Inspection
11/04/06	7:30 AM	3:30 PM	5	42 -55 F	Clear	U/W Inspection
11/05/06	7:30 AM	3:30 PM	5	42 -55 F	Clear	U/W Inspection
11/06/06	7:30 AM	3:30 PM	5	42 -55 F	Clear	U/W Inspection
11/07/06	8:00 AM	4:00 PM	4	42 -55 F	Clear	U/W Inspection
11/21/06	7:30 AM	3:30 PM	5	42 -55 F	Clear	DIDSON Sonar imaging investigation



NYS DOT BRIDGE DIVING  
INSPECTION & CONDITION REPORT

R C MP  
8 6 2 9 , 0 8

SHEET 7 OF 35  
DATE 11/07/06

GENERAL SSU SUMMARY

SPAN #:	0 0 2	UNIT CODE:	P R R	Length:	100	Width:	50
SSU Type:	<input type="checkbox"/> Concrete Solid Stem <input checked="" type="checkbox"/> Dry/Mortared Stone Masonry <input type="checkbox"/> Steel Sheetpile Cell or Caisson <input type="checkbox"/> Other						
SSU Foundation:	<input type="checkbox"/> On Piles: ( <input type="checkbox"/> Timber <input type="checkbox"/> Steel H <input type="checkbox"/> Concrete <input type="checkbox"/> Steel Pipe ) <input type="checkbox"/> On Soil <input checked="" type="checkbox"/> On Bedrock <input type="checkbox"/> Unknown Type <input type="checkbox"/> Other:						
Channel Bottom	<input checked="" type="checkbox"/> Natural: <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulders <input type="checkbox"/> Cobbles <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Organics <input checked="" type="checkbox"/> Coarse or Medium Sand <input checked="" type="checkbox"/> Fine Sand or Silt <input type="checkbox"/> Other:						
	<input checked="" type="checkbox"/> Placed: <input checked="" type="checkbox"/> Rip Rap, Large Stone, or Rubble Fill <input checked="" type="checkbox"/> Concrete Overpour, Jacket or Apron <input type="checkbox"/> Other:						
Scour Protection	Does any Scour Protection exist? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    Is it shown on plans? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes						
	Is it functioning adequately? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    No: Explain: _____						

Compare Soundings to Previous

Up to 6 ft of scour on the east elevation and fill up to 5 ft on the west elevation has occurred since the 2002 underwater inspection. Previous inspection used an assumed waterline elevation of +1.00 which may be in error.

Major Findings:

Large void area behind outer timber cribwall. Void is located 29 ft below water, is up to 2 ft high and extends 56 ft along the west face, and 16 ft along the south face. Penetrations into the void over 6 ft deep.

Limits to Performing Inspection:     No     Yes:

SPAN #:	0 0 3	UNIT CODE:	P R R	Length:	100 ft	Width:	60 ft
SSU Type:	<input type="checkbox"/> Concrete Solid Stem <input checked="" type="checkbox"/> Dry/Mortared Stone Masonry <input type="checkbox"/> Steel Sheetpile Cell or Caisson <input type="checkbox"/> Other						
SSU Foundation:	<input type="checkbox"/> On Piles: ( <input type="checkbox"/> Timber <input type="checkbox"/> Steel H <input type="checkbox"/> Concrete <input type="checkbox"/> Steel Pipe ) <input type="checkbox"/> On Soil <input checked="" type="checkbox"/> On Bedrock <input type="checkbox"/> Unknown Type <input type="checkbox"/> Other:						
Channel Bottom	<input checked="" type="checkbox"/> Natural: <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulders <input type="checkbox"/> Cobbles <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Organics <input checked="" type="checkbox"/> Coarse or Medium Sand <input checked="" type="checkbox"/> Fine Sand or Silt <input type="checkbox"/> Other:						
	<input type="checkbox"/> Placed: <input type="checkbox"/> Rip Rap, Large Stone, or Rubble Fill <input type="checkbox"/> Concrete Overpour, Jacket or Apron <input type="checkbox"/> Other:						
Scour Protection	Does any Scour Protection exist? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    Is it shown on plans? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes						
	Is it functioning adequately? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    No: Explain: _____						

Compare Soundings to Previous

Fill up to 5 ft has occurred on the west elevation and fill up to 10 ft on the east elevation since the 2002 underwater inspection. Previous inspection used an assumed waterline elevation of +1.00 which may be in error.

Major Findings:

Large void area on on the east face between the timber grillage and timber cribwall. Void area is located 22 ft below water and is approximately 2 ft to 4 ft high and 2 ft to 6 ft deep.

Limits to Performing Inspection:     No     Yes:



GENERAL SSU SUMMARY

SPAN #:	0 0 4	UNIT CODE:	P R R	Length:	100 ft	Width:	60 ft
SSU Type:	<input type="checkbox"/> Concrete Solid Stem <input checked="" type="checkbox"/> Dry/Mortared Stone Masonry <input type="checkbox"/> Steel Sheetpile Cell or Caisson <input type="checkbox"/> Other						
SSU Foundation:	<input type="checkbox"/> On Piles: ( <input type="checkbox"/> Timber <input type="checkbox"/> Steel H <input type="checkbox"/> Concrete <input type="checkbox"/> Steel Pipe ) <input type="checkbox"/> On Soil <input checked="" type="checkbox"/> On Bedrock <input type="checkbox"/> Unknown Type <input type="checkbox"/> Other:						
Channel Bottom	<input checked="" type="checkbox"/> Natural: <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulders <input type="checkbox"/> Cobbles <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Organics <input type="checkbox"/> Coarse or Medium Sand <input checked="" type="checkbox"/> Fine Sand or Silt <input type="checkbox"/> Other:						
	<input checked="" type="checkbox"/> Placed: <input checked="" type="checkbox"/> Rip Rap, Large Stone, or Rubble Fill <input type="checkbox"/> Concrete Overpour, Jacket or Apron <input type="checkbox"/> Other:						
Scour Protection	Does any Scour Protection exist? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    Is it shown on plans? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes Is it functioning adequately? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    No: Explain: _____						
<b>Compare Soundings to Previous</b>							
No sounding data is available for comparison.							
<b>Major Findings:</b>							
Typical gaps between the timber cribbing members approximately 1 in. to 2 in. high with penetration into the gaps from 1 ft to 4 ft deep.							
Limits to Performing Inspection: <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes:							

SPAN #:	0 0 5	UNIT CODE:	P R R	Length:	100 ft	Width:	60 ft
SSU Type:	<input type="checkbox"/> Concrete Solid Stem <input checked="" type="checkbox"/> Dry/Mortared Stone Masonry <input type="checkbox"/> Steel Sheetpile Cell or Caisson <input type="checkbox"/> Other						
SSU Foundation:	<input type="checkbox"/> On Piles: ( <input type="checkbox"/> Timber <input type="checkbox"/> Steel H <input type="checkbox"/> Concrete <input type="checkbox"/> Steel Pipe ) <input type="checkbox"/> On Soil <input checked="" type="checkbox"/> On Bedrock <input type="checkbox"/> Unknown Type <input type="checkbox"/> Other:						
Channel Bottom	<input checked="" type="checkbox"/> Natural: <input type="checkbox"/> Bedrock <input type="checkbox"/> Boulders <input type="checkbox"/> Cobbles <input checked="" type="checkbox"/> Gravel <input type="checkbox"/> Organics <input checked="" type="checkbox"/> Coarse or Medium Sand <input checked="" type="checkbox"/> Fine Sand or Silt <input type="checkbox"/> Other:						
	<input type="checkbox"/> Placed: <input type="checkbox"/> Rip Rap, Large Stone, or Rubble Fill <input type="checkbox"/> Concrete Overpour, Jacket or Apron <input type="checkbox"/> Other:						
Scour Protection	Does any Scour Protection exist? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    Is it shown on plans? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes Is it functioning adequately? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes    No: Explain: _____						
<b>Compare Soundings to Previous</b>							
No sounding data is available for comparison.							
<b>Major Findings:</b>							
Typical gaps between the timber cribbing members approximately 1 in. to 2 in. high with penetration into the gaps from 1 ft to 4 ft deep.							
Limits to Performing Inspection: <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes:							



## UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: 6 SHEET 9 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06

SPAN NO. & UNIT CODE	RATING ITEM	RATING	REMARKS
002PRR	24	3	Voids - Voids created due to loss of ballast stone from outer timber cribwall.
			Void measures up to 2 ft high at the southwest corner, and extends 56 ft to the north along the west face, and 16 ft along the south face. Penetration into the void is greater than 6 ft.
	25	4	Holes - Several intermittent holes through the outer timber cribwall.
			Holes measure up to 1 ft high by 1 ft wide with penetration up to 4 ft.
	26	4	Structural Damage - Missing and rotted outer cribwall timbers on the south and west faces of the pier.
	27	4	Non-structural damage - loss of ballast stone from outer cribwall.
	28	4	Displacement - Several horizontal timbers are displaced up to 1 ft vertically.
	29	4	Missing Elements - cribwall is missing original layer of vertical timber sheathing.
	30	3	Loss of fill - Loss of balast stone fill in outer cribwall layer.
	34	9	Structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	35	9	Non-structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	36	9	Spalls - Concrete elements are covered by stone masonry veneer or timber cribwall.
	37	4	Erosion/Scaling - penetrations from 1 ft to 4 ft into the concrete fill behind the outer timber cribwall.
	39	4	Grout Loss - Approximately 25 percent loss of grout from the masonry joints.
	42	4	Splitting - Ends of most timber cribwall and grillage members split up to 2 in. wide and up to 1 ft long.
	44	4	Rot - Outer layer of timber cribwall and grillage exhibit approximately 1 in. to 2 in. loss of section due to rot, creating 1 in. to 3 in. gaps between the timbers.
	45	4	Fasteners - Most of the exposed steel pins fastening the timbers exhibit 50 percent to 100 percent loss of cross-sectional area.
	46	4	Missing elements - cribwall is missing original layer of vertical timber sheathing.



## UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: 6 SHEET 10 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06

SPAN NO. & UNIT CODE	RATING ITEM	RATING	REMARKS
003PRR	24	3	Voids - Voids created due to loss of concrete from under the timber grillage.
			Void measures up to 1 ft to 2 ft high, and extends along the entire east face of the pier, depth of the void is up to 6 ft.
	25	4	Holes - Several intermittent holes through the outer timber cribwall.
			Holes measure up to 1 ft high by 1 ft wide with penetration up to 4 ft.
	26	4	Structural Damage - Missing and rotted outer cribwall timbers on the south and west faces of the pier.
	27	4	Non-structural damage - loss of ballast stone from outer cribwall.
	28	4	Displacement - Several horizontal timbers are displaced up to 1 ft vertically.
	29	4	Missing Elements - cribwall is missing original layer of vertical timber sheathing.
	30	3	Loss of fill - Loss of balast stone fill in outer cribwall layer.
	34	9	Structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	35	9	Non-structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	36	9	Spalls - Concrete elements are covered by stone masonry veneer or timber cribwall.
	37	4	Erosion/Scaling - penetrations from 1 ft to 4 ft into the concrete fill behind the outer timber cribwall.
	39	4	Grout Loss - Approximately 25 percent loss of grout from the masonry joints.
	42	4	Splitting - Ends of most timber cribwall and grillage members split up to 2 in. wide and up to 1 ft long.
	44	4	Rot - Outer layer of timber cribwall and grillage exhibit approximately 1 in. to 2 in. loss of section due to rot, creating 1 in. to 3 in. gaps between the timbers.
	45	4	Fasteners - Most of the exposed steel pins fastening the timbers exhibit 50 percent to 100 percent loss of cross-sectional area.
	46	4	Missing elements - cribwall is missing original layer of vertical timber sheathing.



## UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: 6 SHEET 11 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06

SPAN NO. & UNIT CODE	RATING ITEM	RATING	REMARKS
004PRR	24	4	Voids - Voids created due to loss of concrete from outer timber cribwall. Penetrations into the voids up to 4 ft deep.
	25	4	Holes - Several intermittent holes through the outer timber cribwall. Holes measure up to 1 ft high by 1 ft wide and penetration up to 4 ft.
	26	4	Structural Damage - Missing and rotted outer cribwall timbers on the south and west faces of the pier.
	27	4	Non-structural damage - loss of ballast stone from outer cribwall.
	29	4	Missing Elements - cribwall is missing original layer of vertical timber sheathing.
	34	9	Structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	35	9	Non-structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	36	9	Spalls - Concrete elements are covered by stone masonry veneer or timber cribwall.
	37	4	Erosion/Scaling - penetrations from 1 ft to 4 ft into the concrete fill behind the outer timber cribwall.
	39	4	Grout Loss - Approximately 25 percent loss of grout from the masonry joints.
	42	4	Splitting - Ends of most timber cribwall and grillage members split up to 2 in. wide and up to 1 ft long.
	44	4	Rot - Outer layer of timber cribwall and grillage exhibit approximately 1 in. to 2 in. loss of section due to rot, creating 1 in. to 3 in. gaps between the timbers.
	45	4	Fasteners - Most of the exposed steel pins fastening the timbers exhibit 50 percent to 100 percent loss of cross-sectional area.
	46	4	Missing elements - cribwall is missing original layer of vertical timber sheathing.



## UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: 6 SHEET 12 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06

SPAN NO. & UNIT CODE	RATING ITEM	RATING	REMARKS
005PRR	24	4	Voids - Voids created due to loss of concrete from outer timber cribwall. Penetration into the voids up to 4 ft deep.
	25	4	Holes - Several intermittent holes through the outer timber cribwall. Holes measure up to 1 ft high by 1 ft wide and penetration up to 4 ft.
	26	4	Structural Damage - Missing and rotted outer cribwall timbers on the south and west faces of the pier.
	27	4	Non-structural damage - loss of ballast stone from outer cribwall.
	29	4	Missing Elements - cribwall is missing original layer of vertical timber sheathing.
	34	9	Structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	35	9	Non-structural cracks - Concrete elements are covered by stone masonry veneer or timber cribwall.
	36	9	Spalls - Concrete elements are covered by stone masonry veneer or timber cribwall.
	37	4	Erosion/Scaling - penetrations from 1 ft to 4 ft into the concrete fill behind the outer timber cribwall.
	39	4	Grout Loss - Approximately 25 percent loss of grout from the masonry joints.
	42	4	Splitting - Ends of most timber cribwall and grillage members split up to 2 in. wide and up to 1 ft long.
	44	4	Rot - Outer layer of timber cribwall and grillage exhibit approximately 1 in. to 2 in. loss of section due to rot, creating 1 in. to 3 in. gaps between the timbers.
	45	4	Fasteners - Most of the exposed steel pins fastening the timbers exhibit 50 percent to 100 percent loss of cross-sectional area.
	46	4	Missing elements - cribwall is missing original layer of vertical timber sheathing.



# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: \_\_\_\_\_ SHEET 13 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06

## RECOMMENDATIONS:

002PRR Repair voids along the west and south faces of the timber cribwall. Fill void areas behind cribwall.  
Repoint stone masonry along the face of the pier.

003PRR Repair voids along the east face of the timber grillage. Fill void areas under the timber grillage.  
Repoint stone masonry along the face of the pier.

004PRR Repoint stone masonry along the face of the pier.


005PRR Repoint stone masonry along the face of the pier.

# SKETCHES

# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN MP 29.08 REGION 8 COUNTY 6 Sheet 14 of 35  
FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

## PLAN VIEW





# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 15 of 35

FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE

FEATURE CROSSED HUDSON RIVER

INSPECTED BY James V. Green


TITLE PIER 2

DATE 11/07/2006

## ELEVATION SKETCH

UNIT: PIER 2

DIVER'S CONFIRMATION: \_\_\_\_\_



Depth: (ft) 2006	61.0	59.0	63.0
Depth: (ft) 2002	64.0	64.0	64.0
STATION: (ft)	0+00	0+50	1+00
VIDEO TIME:	Not taken due to poor visibility		
UNDERMINE HORIZ./VERT.	NONE		
FOUNDATION TYPE:	STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB		
REMARKS:	N/A		
PILE TYPE:	N/A		
PILE LENGTH:	N/A		



# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT


BIN 29.08 REGION 8 COUNTY 6 Sheet 16 of 35

FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER


INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

DATE 11/07/2006

UNIT: PIER 2

DIVER'S CONFIRMATION: 

## ELEVATION SKETCH



Depth: (ft) 2006	63.0	53.0	66.0
Depth: (ft) 2002	63.0	47.0	63.0
STATION: (ft)	1+00	0+50	0+00

VIDEO TIME: Not taken due to poor visibility

UNDERMINE HORIZ./VERT. NONE

FOUNDATION TYPE: STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB PILE TYPE: N/A PILE LENGTH: N/A

REMARKS:

# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 17 of 35


FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER

INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

UNIT: PIER 3

DIVER'S CONFIRMATION: 

## ELEVATION SKETCH



**PIER 3**  
**WEST ELEVATION VIEW**  
N.T.S.

Depth: (ft) 2006	54.0	46.0	47.0
Depth: (ft) 2002	52.0	41.0	49.0
STATION: (ft)	0+00	0+50	1+00

VIDEO TIME: Not taken due to poor visibility

UNDERMINE HORIZ./VERT.: NONE

FOUNDATION TYPE: STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB

PILE TYPE: N/A  
PILE LENGTH: N/A

REMARKS:



# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 18 of 35

FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE


FEATURE CROSSED HUDSON RIVER

INSPECTED BY James V. Green


TITLE P.E./DIVER

DATE 11/07/2006

UNIT: PIER 3

DIVER'S CONFIRMATION: 

## ELEVATION SKETCH



DEPTH (ft)	STATION	REMARKS
50.0	1+00	2002 MUDDLINE
49.0	1+00	VOID 2' TO 4' H x 75' L x 2' TO 4' DEEP
38.0	0+50	2006 MUDDLINE
51.0	51+00	TOP OF CRIB EL. -22'
50.0	50+00	TOP OF GRILLAGE EL. -11'
0+00	0+00	EL. +5.0 (PER PLANS)

VIDEO TIME: Not taken due to poor visibility

UNDERMINE HORIZ./VERT. NONE

FOUNDATION TYPE: STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB

PILE TYPE: N/A

PILE LENGTH: N/A

REMARKS:




# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 19 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

UNIT: PIER 4 DIVER'S CONFIRMATION: 

## ELEVATION SKETCH



**PIER 4**  
**WEST ELEVATION VIEW**  
 N.T.S.

Depth: (ft) 2006	58.0	39.0	50.0
Depth: (ft) 2002	N/A	N/A	N/A
STATION: (ft)	0+00	0+50	1+00
VIDEO TIME:	Not taken due to poor visibility		
UNDERMINE HORIZ./VERT.	NONE		
FOUNDATION TYPE:	STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB		
REMARKS:	PILE TYPE: _____ PILE LENGTH: _____ N/A N/A		

# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 20 of 35

FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE

FEATURE CROSSED HUDSON RIVER

INSPECTED BY James V. Green


TITLE P.E./DIVER

DATE 11/07/2008

UNIT: PIER 4

DIVER'S CONFIRMATION: 

## ELEVATION SKETCH



### PIER 4 EAST ELEVATION VIEW

N.T.S.

Depth: (ft) 2006	55.0	41.0	54.0
Depth: (ft) 2002	N/A		
STATION: (ft)	1+00	0+50	0+00
VIDEO TIME:	Not taken due to poor visibility		
UNDERMINE HORIZ./VERT.	NONE		

FOUNDATION TYPE:	STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB	PILE TYPE:	N/A	PILE LENGTH:	N/A
REMARKS:					




# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 21 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

UNIT: PIER 5 DIVER'S CONFIRMATION: [Signature]

## ELEVATION SKETCH



**PIER 5**  
**WEST ELEVATION VIEW**  
 N.T.S.

Depth: (ft) 2006	52.0	45.0	54.0
Depth: (ft) 2002	N/A		
STATION: (ft)	0+00	0+50	1+00
VIDEO TIME:	Not taken due to poor visibility		
UNDERMINE HORIZ./VERT.	NONE		
FOUNDATION TYPE:	STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB		
REMARKS:	PILE TYPE: N/A PILE LENGTH: N/A		




# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 22 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

UNIT: PIER 5 DIVER'S CONFIRMATION: 

## ELEVATION SKETCH




**PIER 5**  
**EAST ELEVATION VIEW**  
N.T.S.

Depth: (ft) 2006	54.0	42.0	53.0	
Depth: (ft) 2002	N/A			
STATION: (ft)	1+00	0+50	0+00	
VIDEO TIME:	Not taken due to poor visibility			
UNDERMINE HORIZ./VERT.	NONE			
FOUNDATION TYPE:	STONE & GRAVEL WITH CONCRETE FILLED TIMBER CRIB			
REMARKS:				PILE TYPE: N/A PILE LENGTH: N/A

# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 23 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006  
 UNIT: PIER 2 DIVER'S CONFIRMATION: [Signature]

## SOUNDING DATA




CHANNEL BOTTOM DESCRIPTION RIP-RAP, CONC. DEBRIS, SILT  
 SCOUR PROTECTION RIP-RAP.



# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 24 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006  
 UNIT: PIER 3 DIVER'S CONFIRMATION: [Signature]


## SOUNDING DATA



WEST FACE

**PLAN VIEW**  
N.T.S.

DATUM: PIER 3  
 DATE 11-03-06 TIME 11:45AM




CHANNEL BOTTOM DESCRIPTION RIP-RAP, CONC. & SILT DEBRIS, SILT  
 SCOUR PROTECTION RIP-RAP.



# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 25 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006  
 UNIT: PIER 4 DIVER'S CONFIRMATION: \_\_\_\_\_

## SOUNDING DATA




# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN 29.08 REGION 8 COUNTY 6 Sheet 26 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

UNIT: PIER 5 DIVER'S CONFIRMATION: [Signature]

## SOUNDING DATA




CHANNEL BOTTOM DESCRIPTION RIP-RAP, CONC. DEBRIS, SILT  
 SCOUR PROTECTION RIP-RAP.



# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN MP 29.08 REGION 8 COUNTY 6 Sheet 27 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

## FATHOMETRIC PLAN






# PHOTOGRAPHS

# UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

BIN MP 29.08 REGION 8 COUNTY 6 Sheet 28 of 35  
 FEATURE CARRIED POUGHKEEPSIE RAILROAD BRIDGE FEATURE CROSSED HUDSON RIVER  
 INSPECTED BY James V. Green TITLE P.E./DIVER DATE 11/07/2006

## PHOTO LOCATION PLAN



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 29 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06



PHOTO NO.: 1  
LOCATION: \_\_\_\_\_  
Upstream

DESCRIPTION: \_\_\_\_\_  
General View  
Looking North

REFERENCES: N/A



PHOTO NO.: 2  
LOCATION: \_\_\_\_\_  
Downstream

DESCRIPTION: \_\_\_\_\_  
General View  
Looking South

REFERENCES: N/A



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 30 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06




PHOTO NO.: 3  
LOCATION: \_\_\_\_\_  
South Elevation  
\_\_\_\_\_  
\_\_\_\_\_

DESCRIPTION: \_\_\_\_\_  
General View  
Looking North  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REFERENCES: N/A  
\_\_\_\_\_



PHOTO NO.: 4  
LOCATION: \_\_\_\_\_  
North Elevation  
\_\_\_\_\_  
\_\_\_\_\_

DESCRIPTION: \_\_\_\_\_  
General View  
Looking South  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REFERENCES: N/A  
\_\_\_\_\_



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 31 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06



PHOTO NO.: 5  
LOCATION: \_\_\_\_\_  
Pier 2  
\_\_\_\_\_  
\_\_\_\_\_

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Southeast  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REFERENCES: N/A  
\_\_\_\_\_




PHOTO NO.: 6  
LOCATION: \_\_\_\_\_  
Pier 2  
\_\_\_\_\_  
\_\_\_\_\_

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Northwest  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REFERENCES: N/A  
\_\_\_\_\_



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 32 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06



PHOTO NO.: 7  
LOCATION: \_\_\_\_\_  
Pier 3  
\_\_\_\_\_  
\_\_\_\_\_

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Southeast  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REFERENCES: N/A  
\_\_\_\_\_



PHOTO NO.: 8  
LOCATION: \_\_\_\_\_  
Pier 3  
\_\_\_\_\_  
\_\_\_\_\_

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Northwest  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

REFERENCES: N/A  
\_\_\_\_\_



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 33 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06



PHOTO NO.: 9  
LOCATION: \_\_\_\_\_  
Pier 4

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Southeast

REFERENCES: N/A




PHOTO NO.: 10  
LOCATION: \_\_\_\_\_  
Pier 4

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Northwest

REFERENCES: N/A



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 34 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06



PHOTO NO.: 11  
LOCATION: \_\_\_\_\_  
Pier 5

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Southeast

REFERENCES: N/A




PHOTO NO.: 12  
LOCATION: \_\_\_\_\_  
Pier 5

DESCRIPTION: \_\_\_\_\_  
General View  
Looking Northwest

REFERENCES: N/A



UNDERWATER BRIDGE INSPECTION AND CONDITION REPORT

M.P.: 29.08 REGION: 8 COUNTY: (6) SHEET 35 OF 35

FEATURE CARRIED: Poughkeepsie RR Bridge FEATURE CROSSED: Hudson River

INSPECTED BY: James V. Green TITLE: On-Site P.E./ Team Leader DATE: 11/07/06




PHOTO NO.: 13  
LOCATION: \_\_\_\_\_  
Pier 2

DESCRIPTION: \_\_\_\_\_  
Didson Sonar image  
of void area on west  
face of pier. Note  
large stone fill.

REFERENCES: \_\_\_\_\_  
BR356c - Item 24  
Rated - 3




PHOTO NO.: 14  
LOCATION: \_\_\_\_\_  
Pier 2

DESCRIPTION: \_\_\_\_\_  
Didson Sonar image  
of void area on west  
face of pier. Note  
inner timber cribwall  
still intact.

REFERENCES: \_\_\_\_\_  
BR356c - Item 24  
Rated - 3