HAZARDOUS MATERIALS

Areas of Known and Potential Concern

Property Name and Address	Environmental Concerns		Recommendation
	Known	Potential	
A - Niagara Parkway –Robert Moses Parkway (Project Corridor)	Former Manufacturing Facilities, Former Hydraulic Canal, Former Railroad Lines	Chemical/Solvent Contamination, Petroleum Contamination, Urban Fill	Fill Previously Placed on the site. Environmental Inspection services during construction if soil contamination is identified.
B - Rainbow Bridge	Former Manufactured Gas Plant, Former Auto Repair Shop	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
C - Entrance Ramp to Robert Moses Parkway – 440 Main Street	Former Gas Station, Former Manufacturing Facility, USTs	Petroleum Contamination, Abandoned USTs,	Environmental Inspection services during construction if soil contamination is identified.
D - Days Inn Niagara – 443 Main Street	Former Auto Repair Shop	Abandoned USTs, Petroleum Contamination	Environmental Inspection services during construction if soil contamination is identified.
E - Three Sisters Trading Post – 454 Main Street	Former Manufacturing Facilities, USTs	Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
F - Star Food Mart – 465 Niagara Street	Gas Station, USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
G - Howard Johnson Hotel – 472 Main Street	Former Manufacturing Facilities, Former Hydraulic Canal	Chemical/Solvent Contamination, Petroleum Contamination, Urban Fill	Fill Previously Placed on the Site. Environmental Inspection services during construction if soil contamination is identified.
H - Former DiFranco Park – 480 Main Street	Former Manufacturing Facilities, Former Hydraulic Canal, Former Railroad Lines	Chemical/Solvent Contamination, Petroleum Contamination, Urban Fill	Fill Previously Placed on the Site. Environmental Inspection services during construction if soil contamination is identified.
I - Rodeway Inn – 492 Main Street	Former Gas Station, Former Auto Repair Shop, USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
J - Sunoco Gas Station – 502 Main Street	Gas Station, USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
K - Vacant Lot – 503 Main Street	Former Gas Station, Former Auto Repair Shop, USTs	Petroleum Contamination, Abandoned USTs	Possible GPR survey. Environmental Inspection services during construction if soil contamination is identified.
L - Aquarium of Niagara – 701 Whirlpool Street	Former Manufacturing Facilities, Former Hydraulic Canal, Former Gas Station, USTs, Former Railroad Line	Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs, Urban Fill	Possible GPR survey. Fill Previously Placed on the Site. Environmental Inspection services during construction if soil contamination is identified.
M - Angelo DelSignore Civic Bldg – 775 3rd Street	USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
N - Vacant Building – 318 Spruce Street	Former Manufacturing Facilities	Chemical/Solvent Contamination	Environmental Inspection services during construction if soil contamination is identified.
O - Vacant Lot – 624-626 Ashland Avenue	Former Auto Sales and Service Facility	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
P - Parking Lot – 808 Cleveland Avenue	Former Gas Station, Former Auto Repair Shop, USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
Q - Henry E. Wrobel Towers – 800 Niagara Avenue	Former Coal yard, Former Railroad lines, Former Gas Station, USTs	Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
R - Vacant Lot – 2201 Whirlpool Street	Former Gas Station, Former Auto Repair Shop, USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
S - Former US Customs House – 2243-2245 Whirlpool Street	Former Gas Station, USTs	Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
T - Whirlpool Bridge – 2250 Whirlpool Street	Former Railroad Lines	Chemical/Solvent Contamination	Environmental Inspection services during construction if soil contamination is identified.
U - Whirlpool Regional Maintenance Center – 2630 Whirlpool Street	Former Garage, Former Manufacturing Facilities, USTs, ASTs	Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.
V - Unifrax Corp. – 2351 Whirlpool Street	Former Manufacturing Facilities, Former Railroad Line, Former Heating Plant	Chemical/Solvent Contamination, Petroleum Contamination	Environmental Inspection services during construction if soil contamination is identified.
W - Former Grand Manor Inc. –2600 Main Street	Former Manufacturing Facilities, UST	Chemical/Solvent Contamination, Petroleum Contamination, Abandoned USTs	Environmental Inspection services during construction if soil contamination is identified.

HAZARDOUS MATERIALS

Sites of Potential Environmental Concern



NIAGARA GORGE CORRIDOR

Robert Moses Parkway Removal Project

MAIN STREET TO FINDLAY DRIVE